


T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 35 Corner common to sections 35, 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species POPULAR  
Diameter 7"  
Bearing S 37 E  
Distance 30 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1917 By E. O. HORST  
Location filed COUNTY BOOK B P. 602  
Monument FIND OLD CORNER STAKE: OLD CORNER BIT: 7"  
POPULAR S 77 E 30 LKS SET NEW STAKE

Evidence of Subsequent Corner Restoration

Year of search 1919 By GLO  
FIND SE BIT - NOW 24" SET 1x36" 1/4 W / BASS CAP  
1/4  
535 / 536  
1919

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

1928 - GLO RESET COR - AS IT WAS OUT OF PLACE  
FROM ROAD CONSTRUCTION  
Bearing Trees, Reference Objects  
R. OAK R. OAK R. OAK  
12" 12" 12"  
N 81-30 E S 46-15 W S 85-30 W  
69 LKS 127 LKS 135 LKS  
1919 TIES 1928 TIE

Subsequent Corner Restoration

Year surveyed 1932 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument CO DITCH SURVEY BK 173  
BOX 3 OF CO DITCH SURVEY BOOKS  
PG 80

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_