


Index No. 421

CASS COUNTY LAND CORNER RECORD

T. 142 R. 28 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S 1/4 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1919 S 1/4  
Original monument 1x36" I.P.W./BRASS 535/536  
CAP 1919

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

○ = Corner

Bearing Trees

Species	<u>MAPLE</u>	<u>W OAK</u>	_____
Diameter	<u>10"</u>	<u>20"</u>	_____
Bearing	<u>N41-30E</u>	<u>N42-30W</u>	_____
Distance	<u>74KS</u>	<u>60KS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1928 By GLO  
Location filed SEC. OF STATE  
Monument CORNER SET IN 1919 WAS PULLED DURING  
ROAD CONSTRUCTION RE-SET THE CORNER FROM P.T.S.

Evidence of Subsequent Corner Restoration

Year of search 1932 By \_\_\_\_\_  
Co. DITCH SURVEY BK 173 BOX 3 OF  
Co. DITCH SURVEY BOOKS PG. 80

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared A000667564

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_