Index No. E 12-13

CASS COUNTY LAND CORNER RECORD

T. 14R R. 30 M. 5TH Coordinates: X _____ Y _____

MC #12 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Bearing Trees

Species	Ash	Willow		
Diameter	6	10		
Bearing	N74W	S51W		
Distance	30 lks	50 lks		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed _____

Monument _____

Corner now falls in Leech Lake

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____