Index No. E 13-14

# CASS COUNTY LAND CORNER RECORD

T. 14R R. 30 M. 5TH Coordinates: X _____ Y _____

MC #10 Corner common to sections 3, 10



O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1873

Original monument POST

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Maple | Maple | | |
| Diameter | 8 | 10 | | |
| Bearing | S 70 E | N 39 E | | |
| Distance | 16 lks | 24 lks | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed _____

Monument _____

Corner now falls in Leech Lake

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____