


Index No. J-14

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
W 7/16 Corner common to sections 10 & 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918
Original monument 1" x 3/16" I.P. w/ Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
	Elm	_____
Diameter	<u>7</u>	<u>7</u>
Bearing	<u>N38W</u>	<u>55 1/2 W</u>
Distance	<u>29 lks</u>	<u>6 lks</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects	
	Elm	Ash
Diameter	<u>17"</u>	<u>11"</u>
Bearing	<u>N75W</u>	<u>N6W</u>
Distance	<u>59.00'</u>	<u>47.90'</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1970
Plot - Leech Lake Park - Chas. Murray 1924

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____