


T. 142 R. 30 M. 574 Coordinates: X _____ Y _____
MC # 26 Corner common to sections 7, 18



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Distance	Trees
<u>Oak</u>	<u>3</u>	<u>27 lks</u>	<u>Oak</u>
<u>Oak</u>	<u>4</u>	<u>23 lks</u>	<u>NISE</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed _____

Monument Set 1" x 36" I.P. w/ Br. Cap on
recess bearing - no evidence found of
original

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman

Set 5 1/2 x 5 1/2 x 60" concrete monument
with brass cap.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>6</u>	<u>S 83 E</u>	<u>168 lks</u>
<u>Oak</u>	<u>10</u>	<u>N 72 1/2 E</u>	<u>184 lks</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance	Cedar Post
<u>Birch</u>	<u>8"</u>	<u>N 44 E</u>	<u>29.80'</u>	<u>4x4x72"</u>
<u>Oak</u>	<u>12"</u>	<u>S 89 E</u>	<u>29.70'</u>	<u>West</u>
<u>Willow</u>	<u>6"</u>	<u>S 83 E</u>	<u>117.0'</u>	<u>1.20'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - BILL OKERMAN - 1970

1999 - CCSO

Find. impl. brass cap mon. set in
concrete pillar up 1.7' wood post is 1.2'
E. of mon. located 38'± DUE EAST of Agency
Bay shoreline. Find 2 B.T.'s w/ tags (RLS 6307)

REF. TIES:

- * 4" G. Ash N 72° W 28.98'
- * 12" Birch N 44° E 29.93'
- * 13" R. Oak S 89° E 116.66'

* distance to dbl. hd. nail