


Index No. L 13

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 13, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>Maple</u>	<u>Oak</u>
Diameter <u>14</u>	<u>8</u>
Bearing <u>N74E</u>	<u>N69W</u>
Distance <u>26 lks</u>	<u>59 lks</u>

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Set 1" x 36" h.P. w/Bv. Cap from
stumps of original BTS

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman
Found GLO monument in good condition;
12" OAK SW6E 36.30' now 21"

Bearing Trees, Reference Objects

Species <u>R.Oak</u>	<u>R.Oak</u>	_____
Diameter <u>12</u>	<u>6</u>	_____
Bearing <u>S66 1/4 E</u>	<u>N72W</u>	_____
Distance <u>55 lks</u>	<u>58 lks</u>	_____

Bearing Trees, Reference Objects

<u>OAK</u>	<u>Maple</u>	<u>OAK</u>
<u>18"</u>	<u>14"</u>	<u>21"</u>
<u>N31E</u>	<u>S9E</u>	<u>S66E</u>
<u>9.00'</u>	<u>29.70'</u>	<u>36.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1966

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____