


Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
N 14 22 Corner common to sections 15, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873 Same as _____
Original monument POST MC

Bearing Trees

Species	<u>Elm</u>	<u>Willow</u>	_____
Diameter	<u>4</u>	<u>3</u>	_____
Bearing	<u>S 28 E</u>	<u>S 38 W</u>	_____
Distance	<u>9 lks</u>	<u>19 lks</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument 1" x 36" I.P. w/ Br. Cap - no evidence of original.

Evidence of Subsequent Corner Restoration

Year of search 1965 By William Okerman
Found GLO monument in good condition. 6" Ash S 46 W 19.80' now 10".

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Ash</u>	_____
Diameter	<u>6</u>	<u>6</u>	_____
Bearing	<u>N 44 1/2 E</u>	<u>S 46 1/4 W</u>	_____
Distance	<u>22 lks</u>	<u>30 lks</u>	_____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Ash</u>	_____
Diameter	<u>8"</u>	<u>10"</u>	_____
Bearing	<u>N 26 W</u>	<u>S 46 W</u>	_____
Distance	<u>16.4'</u>	<u>19.8'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By CERTIFICATE - BILL OKERMAN - 1965

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____