


Index No. P-Q-2

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
SMC Corner common to sections 19 on W. 1/16 line



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1920
Original monument 1" x 3/16" I.P. w/Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>R. Oak</u>	<u>R. Oak</u>	
Diameter <u>5</u>	<u>6</u>	
Bearing <u>S 41 1/2 E</u>	<u>S 39 W</u>	
Distance <u>43 lks</u>	<u>51 lks</u>	

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1967 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.
5" R. Oak S 41 1/2 E 28.40' now 11".

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>Oak</u>	<u>Elm</u>	
Diameter <u>6"</u>	<u>4"</u>	
Bearing <u>S 62 E</u>	<u>S 22 W</u>	
Distance <u>25.90'</u>	<u>61.10'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1967

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____