


T. 142 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 29 Corner common to sections 20, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species J. Pine Spruce \_\_\_\_\_  
Diameter 8 6 \_\_\_\_\_  
Bearing S 19 E N 71 W \_\_\_\_\_  
Distance 47 lks 31 lks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1917 By GLO  
Location filed \_\_\_\_\_  
Monument Set 1" x 3/8" I.P. w/ Br. Cap at  
proportional point. - no evidence found of  
original.

Evidence of Subsequent Corner Restoration

Year of search 1966 By William Okerman  
Set 6" x 2' cylindrical concrete monument  
with 3" stamped bronze tablet 6" below  
road surface.

Bearing Trees, Reference Objects

Species J. Pine J. Pine \_\_\_\_\_  
Diameter 10 11 \_\_\_\_\_  
Bearing N 4 E S 37 W \_\_\_\_\_  
Distance 55 lks 14 lks \_\_\_\_\_

Bearing Trees, Reference Objects

J. PINE J. PINE J. PINE  
7" 6" 13"  
N 55 W N 44 W N 10 W  
59.70' 54.60' 29.65'

R-7

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1966

1999 - LANDECKER + ASSOC.  
Cert. of Survey shows USFS  
brass cap monument found, Dwn. 0.9'  
and 8' S of E TWP. RD. 32

REF. TIES:  
17" R. Oak S 53° W 74.60' (B.T. tag)  
8" Tw. R. Oak N 38° W 47.43'  
6" W. Pine N 48° E 61.65'  
14" J. Pine (old B.T.) N 10° W 29.65'