


Index No. S-11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
CN 7/16 Corner common to sections 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1" x 36" I.P. w/Br. top

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>Poplar</u>	<u>R. Oak</u>
Diameter <u>6</u>	<u>13</u>
Bearing <u>N62°4'E</u>	<u>N36°4'W</u>
Distance <u>52.2 lks</u>	<u>61 lks</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1964 By William Okerman  
Location filed \_\_\_\_\_  
Monument found GLO monument in good condition

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>Maple</u>	<u>Oak</u>	<u>Oak</u>
Diameter <u>8"</u>	<u>8"</u>	<u>25"</u>
Bearing <u>S14°W</u>	<u>S84°W</u>	<u>N34°W</u>
Distance <u>16.1'</u>	<u>5.0'</u>	<u>37.0'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_