


Index No. S-7

CASS COUNTY LAND CORNER RECORD



T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.N. ~~110~~ 110 Corner common to sections 2-9

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1" x 36" I.P. w/Br Lap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>N. Pine</u>	<u>Pine</u>	_____	_____
Diameter	<u>24</u>	<u>12</u>	_____	_____
Bearing	<u>N68°4E</u>	<u>N10W</u>	_____	_____
Distance	<u>136 lks</u>	<u>42 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1999 By CCSO  
Fnd. incl. 2 1/2" ADIP down 0.1' in bit.  
Located 11' W & 13 and B N & Agency Bay Rd.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>W. Pine</u>	<u>N. Pine</u>	<u>W. Pine</u>
<u>5"</u>	<u>15"</u>	<u>24"</u>
<u>N50°W</u>	<u>N76°E</u>	<u>S74°W</u>
<u>79.27'</u>	<u>73.65'</u>	<u>98.10'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_