Index No. T-10

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____

CW 1/16 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918

Original monument 1"x36" I.P. w/Br. Cap

Bearing Trees

Species	Poplar	W. Oak		
Diameter	3	6		
Bearing	N 49 E	S 6½ E		
Distance	48 lks	196 lks		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1989 By USFS

Location filed USFS Cass Lake

Monument USFS Brass Cap

Bearing Trees, Reference Objects

Species	Ash	Maple	R. Oak	Sign Post
Diameter	6"	9"	8"	
Bearing	N 52° W	S 30° E	S 3° W	North
Distance	90.07	85.35	55.57	47'
	16d spk	60d spk	60d spk	

Evidence of Subsequent Corner Restoration

Year of search 3/2001 By CCSO

Found USFS monument, flush, 1.5' S of & Co. Rd. #153. 1989 Oak BT SW is a snag.

Bearing Trees, Reference Objects

Maple				
8"				
S 17° W				
83.84*				

*distance to double head nail

T-10

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____