


Index No. T-9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 29 Corner common to sections 29:28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	<u>J. Pine</u>	<u>J. Pine</u>	_____
Diameter	<u>7</u>	<u>8</u>	_____
Bearing	<u>N 47 W</u>	<u>S 50 E</u>	_____
Distance	<u>12 lks</u>	<u>20 lks</u>	_____

(28)?

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLC

Location filed _____

Monument Set 1" x 36" I.P. w/ Br. Cap from stumps of original BTs.

Evidence of Subsequent Corner Restoration

Year of search 1960 By (a Hunt Dept. Co RD #153 (Webster Road))

Found brass cap

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>J. Pine</u>	_____
Diameter	<u>10</u>	<u>10</u>	_____
Bearing	<u>N 13 E</u>	<u>S 48 1/2 W</u>	_____
Distance	<u>41 lks</u>	<u>40 lks</u>	_____

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>R. Pine</u>	_____
Diameter	<u>6"</u>	<u>10"</u>	_____
Bearing	<u>West</u>	<u>SSE</u>	_____
Distance	<u>16.6'</u>	<u>8.3'</u>	_____

T-9

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO

Location filed CCSO

Monument Found GLC Brass Cap, near PF of old Rd. Grade, 45'± W. of Road Grade, 50'± E. of swamp. Also found 1989 witness trees as follows:

- 13" N. Pine N 30° W, 28.20' to 60d spk
- 11" N. Pine N 55° E, 57.67' to 60d spk
- 16" N. Pine S 37° W, 8.25' to 60d spk
- Steel sign post N and S. 3.85'

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By LANDECKER & ASSOC.

Cert. of Survey shows a GLC Brass cap monument found

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____