


Index No. V-16-17

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
MC Corner common to sections 27:34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1917
 Original monument 1" x 3/16" I.P. w/ Br. cap
8.76 chains east of original M.C.

| Species | Bearing | Trees |
|---------------------------|---------------|-------|
| <u>Poplar</u> | <u>Oak</u> | |
| Diameter <u>16</u> | <u>4</u> | |
| Bearing <u>S 74 1/2 W</u> | <u>N 58 W</u> | |
| Distance <u>17 lks</u> | <u>16 lks</u> | |

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

| Species | Bearing | Trees |
|----------------|---------|-------|
| _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

| Species | Bearing | Reference Objects |
|----------------|---------|-------------------|
| _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

| Species | Bearing | Reference Objects |
|----------------|---------|-------------------|
| _____ | _____ | _____ |
| Diameter _____ | _____ | _____ |
| Bearing _____ | _____ | _____ |
| Distance _____ | _____ | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____