


Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
N 14 32 Corner common to sections 29, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. Pine</u>	<u>W. Pine</u>	
Diameter <u>18</u>	<u>14</u>	
Bearing <u>N 33 W</u>	<u>S 1 1/2 E</u>	
Distance <u>31 lks</u>	<u>45 lks</u>	

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Set 1" x 36" I.P. w / Br. Cap at proportional point - no evidence of original.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species <u>R. Oak</u>	<u>house</u>
Diameter <u>12</u>	
Bearing <u>S 85 1/2 E</u>	<u>N 20 1/2 E</u>
Distance <u>379 lks</u>	

Raised mound of stone North

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By LANDECKER + ASSOC.
Cert. of Survey shows that a mag nail was set as corner.
CCSO also find P.K. - Located 4.5' E of E CSAH 13 and 2.4' N E CO. RD. 15.3.

REF. TIES:

<u>6" Aspen</u>	<u>S 88° W</u>	<u>103.67' (B.T. tag)</u>
<u>12" Tw. R. Oak</u>	<u>N 42° W</u>	<u>111.99'</u>
<u>11" Maple</u>	<u>N 75° E</u>	<u>126.41'</u>
<u>5" R. Pine</u>	<u>S 45° E</u>	<u>94.32'</u>

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____