


Index No. X-2

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
CW 1/16 Corner common to sections 31



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1917  
 Original monument 1" x 3/16" I.P. w/ Br. Cap

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Bearing Trees**

Species	Bearing	Trees
<u>R. Oak</u>	<u>R. Oak</u>	_____
<u>4</u>	<u>12</u>	_____
<u>N20E</u>	<u>S6 1/2 W</u>	_____
<u>13 lbs</u>	<u>194 lbs</u>	_____

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed 1982 By Freeman-Hummitzsch  
 Location filed Survey technician - Foster  
 Monument End brass cap in trees of Stevenson Certificate  
U.S. F.S. "Red Line" runs N-S and east from this  
point

**Evidence of Subsequent Corner Restoration**  
 Year of search 1981 By Gary Stevenson  
 Found GLO monument in good condition.

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>9"</u>	<u>11"</u>	<u>8"</u>
<u>N50W</u>	<u>N60E</u>	<u>N50E</u>
<u>31.23'</u>	<u>16.95'</u>	<u>21.31'</u>

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - Gary Stevenson - 1982  
Doc. # 265362

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_