


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. Pine</u>	<u>W. Pine</u>	_____	_____
Diameter	<u>18</u>	<u>30</u>	_____	_____
Bearing	<u>N73 1/2 W</u>	<u>N15 E</u>	_____	_____
Distance	<u>51 lks</u>	<u>95 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO
Location filed _____
Monument Set 1" x 3/8" I.P. w/ Br. Cap at
proportional point - no evidence of
original.

Evidence of Subsequent Corner Restoration

Year of search 1981 By Gary Stevenson
Found GLO monument in good condition.
Sept. 1911, Twp rd order shows no survey

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>W. Oak</u>	_____	_____
Diameter	<u>6</u>	<u>6</u>	_____	_____
Bearing	<u>N38 1/2 E</u>	<u>S62 W</u>	_____	_____
Distance	<u>127 lks</u>	<u>169 lks</u>	_____	_____

Bearing Trees, Reference Objects

<u>B. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
<u>10"</u>	<u>11"</u>	<u>9"</u>	<u>12"</u>
<u>S88 W</u>	<u>S2 E</u>	<u>N88 E</u>	<u>N39 E</u>
<u>60.23'</u>	<u>48.82'</u>	<u>24.23'</u>	<u>83.8'</u>

(1917 BT)

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc # 265257

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____