


Index No. X 9

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 514 Coordinates: X _____ Y _____
E 1/4 32 Corner common to sections 32, 33



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>Pine</u>	<u>Pine</u>	_____	_____
Diameter	<u>36</u>	<u>24</u>	_____	_____
Bearing	<u>S19 E</u>	<u>N67 W</u>	_____	_____
Distance	<u>35 lks</u>	<u>19 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed _____
Monument Set 1" x 36" li.P. w/Br. cap at
proportional point - no evidence of original.

Evidence of Subsequent Corner Restoration

Year of search 11/03 By Landecker & Assoc.
Cert. of Survey indicates Brass Cup
monument found.

Oct 1914, Top rd order shows no survey

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Birch</u>	_____	_____
Diameter	<u>4</u>	<u>3</u>	_____	_____
Bearing	<u>S32 E</u>	<u>N70 W</u>	_____	_____
Distance	<u>87 lks</u>	<u>42 lks</u>	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____