


Index No. Y-22

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SW 1/16 Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918  
Original monument 1" x 3/16" I.P. w/ Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>J. Pine</u>	<u>Poplar</u>
Diameter <u>6</u>	<u>10</u>
Bearing <u>N51°14'W</u>	<u>S82°3/4'W</u>
Distance <u>114 lbs</u>	<u>125 lbs</u>

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1918/1981 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found 1" x 3/16" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species <u>B. Oak</u>	<u>B. Oak</u>	<u>Poplar</u>
Diameter <u>5"</u>	<u>6"</u>	<u>9"</u>
Bearing <u>N16°39'W</u>	<u>S53°36'E</u>	<u>S58°24'W</u>
Distance <u>42.40'</u>	<u>34.31'</u>	<u>26.09'</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WALT Curo - 1981  
Doc # 262605

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_