


Index No. Y-23

CASS COUNTY LAND CORNER RECORD

T. 142 R. 30 M. 5th Coordinates: X _____ Y _____
CS 116 Corner common to sections 36



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1" x 36" I.P. w/ Br. cap

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species J. Pine N. Pine _____
 Diameter 6 9 _____
 Bearing N40°45'E N79°20'W _____
 Distance 143 lks 20 lks _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1981 By WALTER CURRO
 Location filed _____
 Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species Birch J. Pine str. Birch Poplar
 Diameter 7" 8" 8" 6"
 Bearing N52°45'W N139°E N60°28'E S39°36'E
 Distance 71.96' 44.4' 41.83' 32.18'
(1918 BT)

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - WALT CURRO - 1981
DOC. # 262406