


T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
MC # 27 Corner common to sections 6



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>y. Pine</u>	<u>y. Pine</u>	_____
Diameter	<u>3"</u>	<u>3"</u>	_____
Bearing	<u>N 50 E</u>	<u>N 58 W</u>	_____
Distance	<u>22 lks</u>	<u>30 lks</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1915 By Malyneux
Location filed microfilm - roll 115 BK 81 P. 26
Monument End corner

Evidence of Subsequent Corner Restoration

Year of search 1991 By David Landecker
Set 2" x 48" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
<u>10"</u>	<u>7"</u>	<u>16"</u>
<u>N 3 W</u>	<u>N 58 E</u>	<u>S 46 W</u>
<u>6.19'</u>	<u>21.89'</u>	<u>6.18'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - David Landecker
Doc # 327265