


Index No. D-24-25

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
WC-Sine $\frac{1}{16}$ Corner common to sections 1



○ = Corner

EXISTING SURVEYS

Original Government Survey p. 57
Year surveyed 1913
Original monument 1" x 3/16" Box Cap

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species J. Pine R. Oak _____
Diameter 10 4 _____
Bearing N75-15W S30W _____
Distance 62 23 elks _____

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1969 By Co Hwy Dept
Location filed Co Rn # 72
Monument Corner replace

Evidence of Subsequent Corner Restoration
Year of search 1970 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects
W. OAK J Pine
8" 12"
N81W N2E
4.50' 10.30'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE Bill Okerman - 1970
Mar. 2003 P. Schoberg #14700
Cert. of Svy. shows mon. found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____