


Index No. E16-17

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC #12 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Y. Pine Birch \_\_\_\_\_  
Diameter 18" 8" \_\_\_\_\_  
Bearing N64E S11 1/2 W \_\_\_\_\_  
Distance 43 lks 23 lks \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1910 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK "A" P 304-305  
Monument SET POST FROM ROOTS OF OLD GOVT BIT:  
18" Y. PINE BIT.  
also on micro film - roll 105 BK50 P. 6

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLD  
No evidence found - no mon. set

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_