


Index No. E-F1

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C.# 49 Corner common to sections 7



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>16"</u>	<u>12"</u>
Bearing	<u>S2SE</u>	<u>West</u>
Distance	<u>17 lbs</u>	<u>41 lbs.</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURRO  
Location filed COUNTY RESURVEY PLAT "E-57"  
Monument \* 2" x 48" I.M. W.C.M.C.

Evidence of Subsequent Corner Restoration

Year of search 1991 By DAVID LANDECKER  
Set 2" x 48" iron pipe with brass cap.

1915 - HERST - microfilm - roll 115 BK 78 P.93  
W.C. 47.52' S. of M.C.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Balsam</u>	<u>Balsam</u>	<u>Elm</u>	<u>Balm Gilead</u>
<u>7"</u>	<u>5"</u>	<u>6"</u>	<u>6"</u>
<u>S50W</u>	<u>S60E</u>	<u>N58E</u>	<u>N40W</u>
<u>27.58'</u>	<u>26.08'</u>	<u>16.60'</u>	<u>39.56'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
District # 329604

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_