


T. 142 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
Smc  $\frac{1}{4}$  Corner common to sections 11



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1" x 36" Br. Cap

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>R. Oak</u>	_____	_____
Diameter	<u>6</u>	_____	_____
Bearing	<u>N10 1/2 E</u>	_____	_____
Distance	<u>95 lbs</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1970 By William Oserman  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>W. Pine</u>	<u>W. Pine</u>
Diameter	<u>6"</u>	<u>15"</u>	<u>18"</u>
Bearing	<u>N16 1/2 E</u>	<u>N10 E</u>	<u>S50 E</u>
Distance	<u>23.70'</u>	<u>31.70'</u>	<u>82.50'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OSERMAN - 1970