Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
N1/4 21 Corner common to sections 16, 21



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Bearing Trees

Species	Birch	Birch		
Diameter	3	3		
Bearing	N22E	S25E		
Distance	10 lks	12 lks		

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO
Location filed COUNTY SURVEY RECORD BOOK B" P54-56
Monument FND OLD GOVT STAKE AND OLD GOVT B.TS DEAD 3" BIRCH N22E 10 LKS, 3" BIRCH S25E 12 LKS, SET 2 1/4 x 48" GALV. I.P. W/CAP
1916, JOHN CURO, COUNTY RESURVEY PLAT "E-59" IM

Bearing Trees, Reference Objects

Species	OAK	OAK		
Diameter	14"	7"		
Bearing	S40-30E	S62W		
Distance	21.47'	31.31'		

1913 THIS

Evidence of Subsequent Corner Restoration

Year of search 1916 By E.B. HORST
COUNTY BOOK "C" P503 FND I.M.
1923, GREENE, BOOK "D" P.120 FND I.M.
- also on microfilm - roll 115 BK92 P. 96-97
1916 - also on microfilm - roll 105 BK54B P.16

Bearing Trees, Reference Objects

N-11

Subsequent Corner Restoration

Year surveyed 1925 By Minn Hwy Dept.
Location filed R/W map in Recorders office - Walker to Cass Lake
Monument
2" iron pipe & iron cap 416.1' W. of ℄

5/01 CCSO found 2 1/4" IP w/plumber cap, up 1.0', witnessed as follows:

4" Maple	N60°W,	7.92'*
5" Maple	S88°E,	25.88'*
3/4" PIP	N4°E,	33.22'

*distance to double head nail

June 1917, Twp order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____