


T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 9 Corner common to sections 14, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Y. Pine</u>	<u>Y. Pine</u>	_____	_____
Diameter	<u>8"</u>	<u>10"</u>	_____	_____
Bearing	<u>S 73 E</u>	<u>N 52 E</u>	_____	_____
Distance	<u>17 lks</u>	<u>19 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1918 By GLO  
Location filed \_\_\_\_\_  
Monument Br. Cap - 1" x 3/8"

Evidence of Subsequent Corner Restoration

Year of search 1970 By William Okerman  
Found GLO monument in good condition.

No evidence of original found

Bearing Trees, Reference Objects

Species	<u>Pine</u>	<u>Pine</u>	_____	_____
Diameter	<u>6"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 60 1/2 E</u>	<u>S 84 1/2 E</u>	_____	_____
Distance	<u>44 lks</u>	<u>13 lks</u>	_____	_____

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	_____	_____	_____
Diameter	<u>12"</u>	_____	_____	_____
Bearing	<u>N 1/2 E</u>	_____	_____	_____
Distance	<u>36.0'</u>	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1970