


Index No. N3

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 504 Coordinates: X _____ Y _____
N1/4 19 Corner common to sections 18, 19



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>y. Pine</u>	<u>Poplar</u>	_____	_____
Diameter	<u>10</u>	<u>6</u>	_____	_____
Bearing	<u>N52E</u>	<u>S89W</u>	_____	_____
Distance	<u>14 lks</u>	<u>53 lks</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E.B. Horst
Location filed COUNTY RESURVEY PLAT "E-59"
Monument 2x48" I.M.
1921, E.B. Horst, Book C 1973, SET 2x48" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1914 By Curro
microfilm - roll 115 BK 928.6
start east from true corner.

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - David Landecker
Doc # 327271
Found 1 1/2" iron pipe tipped. Set 2 1/2" x 48"
iron pipe with stamped brass cap. TIES:
10" Poplar N80 W 50.85; 8" Oak S43 W
9.17; 9" Poplar N27 E 8.50

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____