


T. 142 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>Birch</u>	<u>3</u>	<u>3</u>
<u>Poplar</u>	<u>3</u>	<u>3</u>
<u>Poplar</u>	<u>3</u>	<u>3</u>
<u>Poplar</u>	<u>3</u>	<u>3</u>
Diameter	<u>3</u>	<u>3</u>
Bearing	<u>N60E</u>	<u>N30W</u>
Distance	<u>6 lks</u>	<u>10 lks</u>
	<u>4 lks</u>	<u>3 lks</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURE

Location filed COUNTY SURVEY RECORD BOOK "B" P. 54-56

Monument FIND OLD CORNER B.T. STUMPS: 3" BIRCH N60E 6 LKS, 3" POPLAR S40W 4 LKS, 3" POPLAR S38E 3 LKS, 3" POPLAR N30W 10 LKS. SET 2" x 4" GALV. I.P. W/ CAP

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. PINE</u>	<u>N. PINE</u>	<u>6"</u>
<u>6"</u>	<u>14"</u>	<u>54.96'</u>
<u>N15-30W</u>	<u>S63W</u>	<u>43.18'</u>
<u>54.96'</u>	<u>43.18'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1915 By JOHN CURE

COUNTY BOOK "B" P. 442-454 FIND 2" x 4" CAPPED PIPE AND HIS 1913 BITS.

1916, JOHN CURE, COUNTY RESURVEY PLAT "E-59" I.M.

1915, JOHN CURE, COUNTY RESURVEY PLAT "E-60" 2" x 4" I.M.

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed 1916 By E.B. HARST

Location filed COUNTY BOOK "C" P. 503

Monument FIND I.M.

also on microfilm - roll 105 BK 548 P. 11

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1991 Certificate - David Landecker

Doc. # 326714

Found 2" capped iron monument. Stamped cap. Ties: 24" N. Pine N15W 54.96' (1913 B.T.); 4" Burr Oak N40E 12.59'; 5" Maple S25E 52.93'; 6" Maple S12W 31.83'.

Feb. 1917, Twp rd order shows no survey

June 1917, Twp rd order shows no survey