


Index No. P 1

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W 14 19 Corner common to sections 19



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1871  
Original monument POST

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Tamarac W. Pine  
Diameter 5" 30"  
Bearing S3W S4E  
Distance 52 lbs 135 lbs

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

O = Corner

Subsequent Corner Restoration  
Year surveyed 1921 By E. B. HORST  
Location filed COUNTY RESURVEY PLAT "E-54"  
Monument 2448" I.I.M.  
1921, E. B. HORST, BOOK "C" P. 472 FND W. LINE BOT.

Evidence of Subsequent Corner Restoration  
Year of search 1990 By David Landecker  
Set 2" x 48" iron pipe with brass cap and 8' steel sign post alongside to stabilize.

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  

Tamarack	Tamarack	Tamarack	Pine
5"	7"	5"	stump
N30E	S75E	S13E	S4E
60.52'	58.33'	56.34'	89.10'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
Doc # 329272

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_