


Index No. X1

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W 1/4 31 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species W. Pine  
Diameter 15"  
Bearing S 35 E  
Distance 6 ft.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By FF. Wilson  
Location filed micro film - roll 115 BK 86 P. 18-19  
Monument Fud weed post & stump of orig B.T.

Evidence of Subsequent Corner Restoration

Year of search 1991 By David Landecker  
Found 1 1/2" iron pipe Set aluminum cap over found pipe.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>Tamarack</u>	<u>W. Pine</u>	<u>Pine</u>
<u>21"</u>	<u>7"</u>	<u>29"</u>	<u>stump</u>
<u>N 9 W</u>	<u>S 80 E</u>	<u>S 6 E</u>	<u>S 85 E</u>
<u>89.90'</u>	<u>53.25'</u>	<u>18.25'</u>	<u>4.0'</u>
<u>(1987 BT)</u>	<u>(1987 BT)</u>	<u>(1935.000)</u>	<u>(1871)</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - David Landecker  
Doc. # 327277

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_