


Index No. Y-23-24

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
wc-smc-5¹/₁₆ Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1" x 3/16" Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees
Species	<u>N. Pine</u>	<u>R. Oak</u>
Diameter	<u>6</u>	<u>3</u>
Bearing	<u>N67¹/₂E</u>	<u>S24E</u>
Distance	<u>56 lbs</u>	<u>67 lbs</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1950 By HAROLD CURD
Location filed COUNTY BOOK 'D' P 98
Monument BRASS CAP WASHED INTO LAKE SET 2X30"
h.p. 104.50' WEST OF SE 1/4

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Baywood - R.F. Schneider - 1971

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____