


Index No. Y-24

CASS COUNTY LAND CORNER RECORD

T. 142 R. 31 M. 5th Coordinates: X _____ Y _____
SE $\frac{1}{16}$ Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1" x 36" Br. Cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>R. Oak</u>	<u>W. Pine</u>	
<u>5</u>	<u>5</u>	
<u>N2-15W</u>	<u>S11/2W</u>	
<u>64 lbs</u>	<u>72 lbs</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1950 By Harold Curo
Location filed County Book D, P408
Monument FIND BRASS CAPPED MONUMENT

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Plat - Baywood - R.F. Schneider - 1971