


Index No. A11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X Y
N81/4 4 Corner common to sections 4 AND 33-144-25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>SPRUCE</u>	<u>BIRCH</u>	
<u>5"</u>	<u>7"</u>	
<u>S50W</u>	<u>N70E</u>	
<u>12 LKS</u>	<u>18 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed SEPT 1984 By K. WHITEHORN
Location filed CERT. OF SURVEY, DOC# 277427
Monument 2" X 5' BRASS CAPPED CONCRETE
FILLED IRON PIPE AT LOST POSITION.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Trees	Reference Objects
<u>ASH</u>	<u>ASH</u>	<u>ASH</u>	
<u>5.3"</u>	<u>12.1"</u>	<u>5.2"</u>	
<u>N49°E</u>	<u>S30E</u>	<u>N77°W</u>	
<u>39.15'</u>	<u>36.83'</u>	<u>41.11'</u>	
<u>16d NAIL</u>	<u>16d nail</u>	<u>16d NAIL</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____