Index No. 415

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____

N¼ 3 Corner common to sections 3 AND 34-144-25



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument POST

Bearing Trees

Species	TAM.	TAM.
Diameter	12"	10"
Bearing	55W	N10E
Distance	30 LKS	20 LKS

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed SEPT 1984 By K. WHITEHORN

Location filed CERT. OF SURVEY, DOC. # 277427

Monument FD. 1" IRON PIPE 13± NW OF RD INTSON DID NOT ACCEPT, SET 2"x5', BRASS CAPPED, CONCRETE FILLED IRON PIPE AT LOST POSITION

Bearing Trees, Reference Objects

Species	8' SFP	8' SFP
Diameter		
Bearing	EAST	WEST
Distance	3.0'	3.0'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____