


T. 143 R. 25 M. 5TH Coordinates: X Y
N14 6 Corner common to sections 6 AND 31-144-25



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1872
 Original monument POST

Bearing Trees
 Species SPRUCE SPRUCE
 Diameter 4" 6"
 Bearing S 4 W N 10 W
 Distance 30 LKS 25 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed SEPT 1984 By R. WHITEHORN
 Location filed CERT OF SURVEY, DOC. # 277427
 Monument 2" X 5' BRASS CAPPED, CONCRETE FILLED
IRON PIPE AT LOST POSITION

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>ASPEN</u>	<u>ASPEN</u>	<u>BALSAM</u>
Diameter	<u>10.5"</u>	<u>8.6"</u>	<u>6.9"</u>
Bearing	<u>N 5° E</u>	<u>S 70° E</u>	<u>N 58° W</u>
Distance	<u>49.73'</u>	<u>20.07</u>	<u>51.46'</u>
	<u>16 d NAIL</u>	<u>16 d NAIL</u>	<u>16 d NAIL</u>

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____