


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X NE 5 Y 4, 5 AND 37, 33 - 144-25  
Corner common to sections



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1872  
 Original monument POST

Bearing Trees			
Species	BEARING	TREE	
<u>SPRUCE</u>	<u>CE</u>	<u>SPRUCE</u>	<u>ASPEN</u>
Diameter	<u>14"</u>	<u>6"</u>	<u>7"</u>
Bearing	<u>N46E</u>	<u>N40W</u>	<u>S59W</u>
Distance	<u>20LKS</u>	<u>30LKS</u>	<u>15LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed SEPT 1984 By K. WHITEHORN, USFS  
 Location filed CERT. OF SURVEY, DOC. # 277427  
 Monument SET 2" X 5" BRASS CAPPED, CONCRETE FILLED IRON PIPE AT LOST POSITION

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
<u>ASH</u>	<u>ELM</u>	<u>ASH</u>
Diameter	<u>7"</u>	<u>8.5"</u>
Bearing	<u>N32°W</u>	<u>N58°E</u>
Distance	<u>12.48</u>	<u>17.57</u>

**Bearing Trees, Reference Objects**

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_