


Index No. E19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
N1/4 11 Corner common to sections 2, 11



○ = Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1872
Original monument POST

Year of search _____ By _____
Monument found _____

Bearing Trees

Original Bearing Trees Found

Species TAM. ASH
Diameter 4" 5"
Bearing S44E N40E
Distance 20LKS 50LKS

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1914 By F.A. Penner
Location filed County Book "C"
Monument SET 4x4x40" CEDAR HUB, PROBABLY

Year of search 1977 By To Hwy Dept
School/Craft State Park Road
I.M. in place - DNR Property corner
1996, 8-15 Found a 1" dia iron pipe w/ cap stamped "MN
CONSERVATION DEPT." Flush left monument as found.
2-22-96 Cert filed by L. Pommerening, RLS 17005, Dec. #
375618

also on microfilm - roll 115 BK94 P.33

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species TAM N. PINE
Diameter 5" 8"
Bearing S33W N69-03W
Distance 53.7' 106.05'

Norway Pine, Tower Pole
14"
N43E S36E
22.08 26.22

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed _____
Monument _____

Year of search _____ By _____

Jan. 1996 L. Pommerening # 17005
Cert. of Sur. shows DNR Conservation Mon. found

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____