

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. J 19

CASS COUNTY LAND CORNER RECORD

143 R. 25 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N114 14 Corner common to sections 11,14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Trees
<u>CEDAR</u>	<u>NRW</u>	<u>SPRUCE</u>
Diameter <u>4"</u>		<u>6"</u>
Bearing <u>NRW</u>	<u>556E</u>	
Distance <u>6LKS</u>	<u>12LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1908 By JAMES FLYNN

Location filed COUNTY BOOK "C" P 184

Monument FIND OLD GOVT B.T.S: 4" CEDAR NRW 6LKS, 6" SPRUCE 556E 12LKS. SET POST

1914, F.A. DENNER, BOOK "C" P 549. SET PROPORTIONALLY.

1908 Corner destroyed - also on microfilm - call 115 8159

Species	Bearing	Trees	Reference Objects
<u>BL ASH</u>	<u>NRW</u>	<u>CEDAR</u>	<u>1, 2, 3, 31</u>
Diameter <u>5"</u>		<u>10"</u>	<u>30"</u>
Bearing <u>S70E</u>	<u>N17W</u>	<u>N3-22E</u>	<u>S38-06E</u>
Distance <u>24.0'</u>	<u>35.0</u>	<u>82.5'</u>	<u>47.9'</u>
	<u>1908 TIES</u>		<u>1914 TIES</u>

Evidence of Subsequent Corner Restoration

Year of search 7/5/84 By Co. Surveyor, USFS

Find P.K.

1965 - Co. Hwy Dept assumed corner in G. E-W Rd, 4 Rd S and 2'E of 4 Rd N.

2 1/2' subcut. ties: W. oak 10" SW 74.6'

10" W. oak SSE 114.2', 10" Basswood SE 81.8'

Bearing Trees, Reference Objects

Sta 690 + 85.3

J-19

Subsequent Corner Restoration

Year surveyed 1965 By J. Ekstrom

Location filed USFS

Monument Road has destroyed BT's

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_