

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. L13

CASS COUNTY LAND CORNER RECORD

143 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Species	Bearing	Trass
<u>TAM.</u>	<u>TAM.</u>	
Diameter <u>8"</u>	<u>7'</u>	
Bearing <u>S60E</u>	<u>N88W</u>	
Distance <u>10 LKS</u>	<u>5 LKS</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1976 By BLM
Location filed SEC. OF STATE
Monument 2 1/2 x 28" ALUM (Post w) ALUM (AP T143N R25W
1/4
S16/S15
1976

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>ASH</u>	<u>ASH</u>	<u>6 OF USFS</u>
Diameter <u>11"</u>	<u>9"</u>	<u>RD #111</u>
Bearing <u>S58E</u>	<u>N12W</u>	<u>WEST</u>
Distance <u>34 LKS</u>	<u>36 1/2 LKS</u>	<u>148 LKS</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____