


Index No. N6

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
W/16 Corner common to sections 17, 20



EXISTING SURVEYS

Original Government Survey

Year surveyed 1976 - BLM T143N R25W  
Original monument 2 1/2 x 28" Alum Post W/16 517  
W/ALUM MAP 1976 520

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species CEDAR CEDAR \_\_\_\_\_  
Diameter 5" 9" \_\_\_\_\_  
Bearing N24E S54W \_\_\_\_\_  
Distance 7 1/2 LKS 16 LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_