Index No. P 9

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____

E 1/4 20 Corner common to sections 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	LINDEN	FIR		
Diameter	6"	4"		
Bearing	N79W	S80E		
Distance	10 LKS	6 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO

Location filed COUNTY SURVEY RECORD BOOK "B" P. 4-11

Monument FND STUMPS OF BOTH BITS AND BOOT OF FIR B.T. (DOWN) Set 4x4x36" CEDAR POST

1914 - F.A. Donner - microfilm - roll 115 BK94 P.8

start east from Curo's Corner

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM

FND 2" I.P. AT CFP - S & W SET 2 1/2 x 28"

ALUM POST W/ ALUM CAP T143N R25W

1/4

S20/S21

1976

Bearing Trees, Reference Objects

Species	N. PINE	DEAD W. PINE	CEDAR F.P.	CEDAR F.P.
Diameter	16"	10"	7"	8"
Bearing	N57-10W	N65-06E	S33-28E	S53-17W
Distance	39.02'	18.22'	6.02'	8.25'
		1913	tres	

Bearing Trees, Reference Objects

ASPEN	ASPEN		
5"	5"		
S68E	S44W		
35 LKS	5 1/2 LKS		

Subsequent Corner Restoration

Year surveyed 1999 By LANDECKER & ASSOC.

Location filed

Monument Found I.M. inpl. (T.F. #21367)

(C of S #498)

Jan. 2003 M. Stefan #12261

Cert. of Svy. shows none found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____