


T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
MC # 31 Corner common to sections 20, 21



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE
Diameter 3"
Bearing N28E
Distance 315 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURR
Location filed COUNTY SURVEY RECORD BOOK 8 P. 4-11
Monument SET CORNER

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM
END USIES 6" CONCRETE POST w/ BRONZE TABLET
T143N R25W
S20/521
MC
1965
RLS NO 6807

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

PINE
30"
N28E
149 LKS
USFS TIE

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1965 FILED IN 1979
Doc # 246311

1991 Certificate - Walter Curr
Doc # 326337
found 2"x160" iron pipe with brass cap.
4" Ash N10E 52.59'
5" Ash N20E 84.31'
24" Pine (dead) N22E 96.58' (1965 BT)
5" Ash N60E 54.43'

Jan 2003 M. Stefan #12261
Cert. of Surv. shows Mon. Found