


Index No. R 11

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N14 28 Corner common to sections 24, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing	Trees
Species	<u>SPRUCE</u>	<u>SPRUCE</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>N8E</u>	<u>S42E</u>	_____
Distance	<u>10 LKS</u>	<u>5 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1914 By F. A. DENNER  
Location filed COUNTY BOOK 2 P. 550  
Monument FOUND CORNER P. 554 NEW B.T.S. (Below)  
also on microfilm - vol 115 BK 94 P. 43

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM  
Found 3" CEDAR Post - SET 2 1/2 x 28" ALUM POST w/ ALUM CAP  
7143N R25W  
1/4 S21  
S28  
1976

Bearing Trees, Reference Objects

Species	<u>CEDAR</u>	<u>CEDAR</u>	_____
Diameter	<u>10"</u>	<u>3"</u>	_____
Bearing	<u>N23-35W</u>	<u>S24-30W</u>	_____
Distance	<u>5.6'</u>	<u>8.3'</u>	_____

Bearing Trees, Reference Objects

<u>BALSAM</u>	<u>BALSAM</u>	_____	_____
<u>3"</u>	<u>4"</u>	_____	_____
<u>N20E</u>	<u>S36E</u>	_____	_____
<u>5 1/2 LKS</u>	<u>12 LKS</u>	_____	_____

R-11

Subsequent Corner Restoration

Year surveyed 3/2001 By CCSO  
Location filed L.R. #2001.011  
Monument Found Aluminum monument,  
in Cedar swamp, 100' E W. of &  
CR # 137. 1983 10" Cedar is S64°W,  
other witnesses good.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1991 Certificate - Walter Curro  
Doc # 326.340  
Found 2 1/2" aluminum monument.  
10" Cedar S49°4W 18.20' (1983 BT)  
8" Cedar N33E 24.83' (1983 BT)  
7" Cedar N88E 24.83'

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_