


Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 25 Corner common to sections 24, 25



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1867  
Original monument POST

**Bearing Trees**

Species	<u>BIRCH</u>	<u>BIRCH</u>	_____	_____
Diameter	<u>6"</u>	<u>4"</u>	_____	_____
Bearing	<u>NE&amp;W</u>	<u>S40W</u>	_____	_____
Distance	<u>21 LKS</u>	<u>10 LKS</u>	_____	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

**Subsequent Corner Restoration**

Year surveyed 1976 By G2D  
Location filed SEC. OF STATE  
Monument END 2" ITASCA Co. ALUM. MON. W/ ALUM. CAP  
T143N  
S2415C  
S251  
R25W

**Bearing Trees, Reference Objects**

Species	<u>POPULAR</u>	<u>MARBLE</u>	<u>STONE</u>	<u>1975</u>
Diameter	<u>8"</u>	<u>4"</u>	<u>4X3X1'</u>	<u>4 OF HWY 6</u>
Bearing	<u>N25E</u>	<u>N57W</u>	<u>S10E</u>	<u>WEST</u>
Distance	<u>20 LKS</u>	<u>17 LKS</u>	<u>41 LKS</u>	<u>113 LKS</u>

ITASCA Co. TIES

**Evidence of Subsequent Corner Restoration**

Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_