


Index No. T 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 28 Corner common to sections 27, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Post

Species	Bearing	Trees
<u>SUGAR</u>	<u>BIRCH</u>	
<u>8"</u>	<u>8"</u>	
<u>567E</u>	<u>N56W</u>	
<u>17LKS</u>	<u>15LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1976 By BLM

Location filed SEC. OF STATE

Monument 2 1/2 x 2 1/2" Alum Post w/ Alum Cap T143N R25W  
114  
520/527  
1976

Evidence of Subsequent Corner Restoration

Year of search 1990 By Walter Curo

Found 1976 BLM monument in good condition.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>TAM Post</u>	<u>3"</u>	<u>EAST</u>	<u>1/2 LK</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Basswood</u>	<u>12"</u>	<u>N20E</u>	<u>23.90'</u>
<u>Maple</u>	<u>4"</u>	<u>S85W</u>	<u>23.43'</u>
<u>Maple</u>	<u>5"</u>	<u>N77E</u>	<u>13.20'</u>
<u>Maple</u>	<u>8"</u>	<u>S35E</u>	<u>30.45'</u>
<u>Basswood</u>	<u>6"</u>	<u>S18E</u>	<u>42.47'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1991 Certificate - Walter Curo  
Doc # 326343

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_