


Index No. V 10

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
W 1/16 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1976 - BLM T143N R25W
Original monument 2 1/2 x 28" Alum Post W 1/16 S2E
W 1/2 20m CAP 1976 S33

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species ELM OAK _____
Diameter 6" 6" _____
Bearing N65E S24W _____
Distance 9 1/2 LKS 40 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1990 By Walter Curo
Location filed _____
Monument Found 1976 BLM monument in
good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species W. Oak W. Oak Elm Basswood
Diameter 8" 6" 6" 9"
Bearing West S24W N65E N62W
Distance 19.03' 26.40' 6.27' 23.25'
(1976 BT) (1976 BT)

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1991 Certificate - Walter Curo
Doc # 326342

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____