Index No. V 14-15

CASS COUNTY LAND CORNER RECORD

T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____

MC # 22 Corner common to sections 27, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1872

Original monument Lost

Bearing Trees

Species	CEDAR	SPRUCE
Diameter	10"	10"
Bearing	S 53½ E	N 4 E
Distance	6 Lks	7 Lks

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____