


Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 143 R. 26 M. 5TH Coordinates: X _____ Y _____
N 1/4 R Corner common to sections R AND 35-144-26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	_____
Diameter	<u>4"</u>	<u>5"</u>	_____
Bearing	<u>S 3 E</u>	<u>N 25 W</u>	_____
Distance	<u>23 LKS</u>	<u>15 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By Wm. OSVENSEN
Location filed _____
Monument SET 2 1/2" x 48" I.P. W/BRASS CAP
AT LOST POSITION

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>CEDAR</u>
Diameter	<u>3"</u>	<u>3"</u>	<u>6"</u>
Bearing	<u>N 60 W</u>	<u>N 10 W</u>	<u>S 52 W</u>
Distance	<u>17.16</u>	<u>9.43</u>	<u>14.04</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERT. BY Wm. OSVENSEN 1990
Doc # 319606

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____